RECEIVED

Revised 10/03

2003 OCT 15 A & STATE OF COLORADO

CORRES. CONTROL INCOMING LTR NO.

Bill Owens, Governor CONNESPONDENCE Douglas H. Benevento, Executive Director CONTROL

00950RF03

Dedicated to protecting and improving the health and environment of the people of Colorado

DUE DATE ACTION

DIST

BERARDINI, J. H. BOGNAR, E. S. BROOKS, L.

DEGENHART, K. R. DIETER, T. J. DIETERLE, S. E.

FERRERA, D. W. GIACOMINI, J. J. HIETT, S. B.

LINDSAY, D. C. LONG, J. W. LYLE, J. L. MARTINEZ, L. A

NAGEL, R. E. NORTH, K.

PARKER, A. M.

RODGERS, A. D. SHELTON, D. C.

SPEARS, M. S. TRICE, K. D. TUOR, N. R.

WIENELLK

AUDU N

NYSHA S

BUTLER, L. CROCKETT, G, A DECK, C. A. 4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530 Phone (303) 692-2000 TDD Line (303) 691-7700 Located in Glendale, Colorado Laboratory and Radiation Services Division 8100 Lowry Blvd. Denver, Colorado 80230-6928 (303) 692-3090



http://www.cdphe.state.co.us

October 9, 2003

Mr. Joe Legare

Acting Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE: Closeout Report for Building 790

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Report for Building 790, dated October 6, 2003. We appreciate being provided this Closeout Report for our information.

As we have previously requested, Closeout Reports should identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition. Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, drain lines, PWLs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship concerns. The discussion provided does not specifically address the infrastructure remaining or removed. It can only be assumed that part of the slab and in-ground utilities remain. As such, we would appreciate being provided a revised Closeout Report for B790 addressing these concerns.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,

cc:

COR. CONTROL X
ADMN. RECORD X
PATS/130

Steven H. Gunderson RFCA Project Coordinator

Reviewed for Addressee Corres. Control RFP

10/15/03 Ac Date By Steve Tower, DOE Tim Rehder, EPA Karen Wiemelt, KH

David Abelson, RFCLOG

Mike Auble, KH Dave Shelton, KH Steve Nesta, KH

Administrative Records Building T130G

Ref. Ltr. #

DOE ORDER #

54001

ADMIN RECORD